

# Cisco MDS 9000 Series Transceiver Firmware Release Notes

Release 9.4(2)

May 11, 2024

The documentation set for this product strives to use bias-free language. For the purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on RFP documentation, or language that is used by a referenced third-party product.

## Introduction

Transceiver firmware upgrade bundles are provided with each NX-OS release. Cisco MDS NX-OS Release 9.4(1) introduces transceiver firmware upgrade capability for supported transceivers on Cisco MDS 9000 platforms. The firmware upgrades are provided to enhance the performance of the transceivers and to resolve known issues.

A transceiver firmware bundle is a file containing updates for multiple transceiver types. Each transceiver firmware update bundle has its own version number. A transceiver firmware bundle may contain new updates for only some transceivers. Firmware for some transceivers may be the same version as the previous firmware bundle.

To download transceiver firmware bundles, go to NX-OS EPLD Updates folder under respective products from <https://software.cisco.com/download/navigator.html>.

## Transceiver Firmware Support Matrix

The following table lists versions of Cisco MDS NX-OS used to install transceiver firmware bundles. The versions must match during installation, but Cisco MDS NX-OS versions can be subsequently upgraded or downgraded without changing the transceiver firmware versions.

**Table 1.** Installation Compatability Matrix

MDS NX-OS Release	Transceiver Firmware Bundle
9.4(2)	nxos-transceiver-firmware.mds.9.4.2.bin

The following table lists the transceiver firmware bundle and supported Cisco MDS 9000 platforms.

**Table 2.** Transceiver Firmware Bundle Support Matrix

Transceiver Firmware Bundle	Cisco MDS 9000 Platform	Product Identifier (PID)
nxos-transceiver-firmware.mds.9.4.2.bin	MDS 9700 48-Port 64-Gbps Advanced Fibre Channel Module	DS-X9748-3072K9
	MDS 9124V Fibre Channel Switch	DS-C9124V-K9
	MDS 9148V Fibre Channel Switch	DS-C9148V-K9
	MDS 9396V Fibre Channel Switch	DS-C9396V-K9

The following table lists the firmware versions for different transceivers that are packaged in the Cisco MDS Release 9.4(2) transceiver firmware bundle.

**Table 3.** Transceiver firmware versions packaged in the transceiver firmware bundle

Transceiver Firmware Bundle	Transceiver PID	Transceiver type/ Manufacturer's part number	Firmware Version
nxos-transceiver-firmware.mds.9.4.2.bin	DS-SFP-FC64G-SW	CISCO-ACCELINK/ NA	1.2
	DS-SFP-FC64G-SW	CISCO-FINISAR/ FTLF8564D1xxx-xx	1.1
	DS-SFP-FC64G-LW	CISCO-INNOLIGHT/ TR-WR13L-NCI	0.24

## Guidelines and Limitations

When you upgrade the transceiver firmware, consider the following guidelines and limitations:

- Transceiver firmware can only be upgraded. After the transceiver firmware is upgraded, it is compatible with all versions of Cisco MDS NX-OS.
- Transceiver firmware upgrade is supported only for the transceiver models that are listed in the [transceiver firmware versions packaged in the transceiver firmware bundle](#) table.
- Transceiver firmware upgrade is supported only on Cisco MDS 9000 platforms that are listed in the [transceiver firmware Support Matrix](#) table.
- Transceiver upgrade is a disruptive procedure. All interfaces, including those in the same module or fabric switch which are not undergoing upgrade will be shut down during the upgrade.
- Do not run interface commands or open another upgrade session on the module or switch while the transceiver is upgrading. This may result in permanent damage to the transceivers.
- Ensure the transceiver power control feature is disabled, so that all transceivers are powered up while the transceiver firmware upgrade proceeds. The status of this feature is automatically checked as part of the transceiver firmware upgrade process.
- To upgrade your software from Cisco MDS NX-OS Release 9.4.2 to a later version, follow these recommended steps:

Disable the Transceiver Power-Control feature: If the Transceiver Power-Control feature is enabled, you must disable it before starting the upgrade. Use the command:

**switch(config)# no system transceiver power-control** to disable the feature.

Verify if the Transceiver Power-Control feature is disabled using the command:

**switch(config)# show system transceiver power-control.**

After the upgrade is complete, you can re-enable the feature with the command:

**switch(config)# system transceiver power-control.**

Affected Switches:

- Cisco MDS 9124V
- Cisco MDS 9148V
- Cisco MDS 9396V

## Determining Transceiver Firmware Version

Use the **show interface fcx/y transceiver details** command to view the current version of firmware on a specific transceiver module. The version of firmware currently running on the transceiver is displayed on the "Firmware version is" line.

### Displaying Current Version of Transceiver Firmware on a Transceiver Module

```
switch# show interface fc1/1 transceiver details
fc1/1 sfp is present
  Name is CISCO-ACCELINK
  Manufacturer's part number is RTX520-571-C99
  Hardware revision is 1.0
  Serial number is ACW27150L32
  Nominal bit rate is 57800 Mb/s
  Link length supported for 50/125um OM3 fiber is 70 m
  FC Transmitter type is short wave laser w/o OFC (SN)
  FC Transmitter supports short distance link length
  Transmission medium is multimode laser with 50 um aperture (M5)
  Supported speeds are - Min speed: 16000 Mb/s, Max speed: 64000 Mb/s
  Cisco extended id is none (0x0)
  Cisco vendor id is (0x1f)
  Cisco part number is 10-3538-01
  Cisco pid is DS-SFP-FC64G-SW
  Cisco version id is V01
  Firmware version is 1.1

  No tx fault, no rx loss, in sync state, diagnostic monitoring type is 0x68
  SFP Diagnostics Information:
-----
                Alarms                Warnings
                High          Low          High          Low
-----
Temperature    46.80 C          75.00 C    -5.00 C    70.00 C    0.00 C
Voltage         3.28 V           3.63 V     2.97 V     3.46 V     3.13 V
Current         7.30 mA          12.00 mA    3.00 mA    11.20 mA    3.60 mA
Tx Power        -0.16 dBm         7.00 dBm  -10.50 dBm  4.00 dBm   -7.50 dBm
Rx Power         0.58 dBm         5.00 dBm  -10.00 dBm  4.00 dBm   -7.00 dBm
Transmit Fault Count = 0
-----
Note: ++ high-alarm; + high-warning; -- low-alarm; - low-warning
switch#
```

---

## Transceiver Firmware Upgrade

This section contains the following topics:

- [Upgrading Transceivers Firmware](#)
- [Upgrading Transceivers in Director Switches](#)
- [Upgrading Transceivers in Fabric Switches](#)
- [Cleaning a Previously Terminated Upgrade](#)

When upgrading transceivers on MDS Director switches, all transceivers in all modules are upgraded by default, or optionally each single module is upgraded. When upgrading transceivers on MDS fabric switches, all supported transceivers will be upgraded together.

**Note:** After transceiver firmware is upgraded, the transceiver firmware remains in the upgraded version even if the transceiver is moved to a different module, switch or interface.

### Upgrading Transceivers

To update firmware in upgradable transceivers, use the **install transceiver** command.

Optionally, a subset of modules to be upgraded can be specified by the user using the **module** keyword. Use comma (,) or range separator (-) to specify a subset of modules. If a specified module number is not present or not supported, it will be ignored and the remaining valid modules will be upgraded. To update firmware on all supported transceivers in a Fabric switch, use the command without the **module** keyword.

Save any pending configuration before starting a transceiver upgrade. The upgrade process may need to reload a Fabric switch after the transceiver upgrades are completed. This depends on which component of the transceiver firmware has been updated. Some transceiver hardware components will utilize the update immediately, however, other transceiver hardware components must be restarted to start using the update. If any of these are updated then the upgrade process will automatically reload the switch. The upgrade will not proceed if there is any pending configuration in the **show running-config diff** command output.

If none of the transceivers require upgrading, the command exits. Otherwise, any transceivers with firmware version lower than the packaged version will be listed in a table and a prompt. The table displays the following details:

- interface number
- current firmware version
- new firmware version
- if reload is required

If you choose to continue, all the interfaces in the corresponding modules are shut down, and all listed transceivers are upgraded in the listed order. The upgrade process may take several minutes to complete. After the upgrade, the status of each upgraded transceiver module is again displayed in a table. If any transceivers must be power cycled, on a Director switch the corresponding modules are reloaded automatically. For a Fabric switch, the whole switch will reload automatically. After the modules or switch become online, the interfaces are left in the same state that they were in, prior to the firmware upgrade.

Transceiver firmware cannot be upgraded when transceiver power control feature is enabled as it is necessary for a transceiver to be powered on to be upgraded. If a transceiver upgrade is attempted with this feature enabled the user is notified and must confirm to proceed. Transceiver power control will be disabled during the upgrade and then re-enabled when the upgrade has completed.

For more information about transceiver power control feature refer to the Cisco MDS 9000 Series Interfaces Configuration Guide, Release 9.x.

## Upgrading Transceivers in Director Switches

### Example: Upgrading transceiver firmware in specified line cards in a Cisco MDS 9700 Series Switch.

```
switch# install transceiver bootflash:nxos-transceiver-firmware.mds.9.4.1a.bin module 3-7,12
Locking current install transceiver session
2024 Jan 15 04:10:38 Starting transceiver firmware upgrade image file /bootflash/nxos-
transceiver-firmware.mds.9.4.1.bin
2024 Jan 15 04:10:38 Extracting transceiver firmware(s) from package
357+1 records in
357+1 records out
234649 bytes (235 kB) copied, 0.00379426 s, 61.8 MB/s
```

```
Version (CISCO-ACCELINK)      : 1.1
Version (CISCO-FINISAR)      : 1.1
```

Upgrading transceivers on module(s): [3, 6, 7, 12]

Collecting interface configuration and transceiver information, please wait.

Transceivers will be upgraded according to following table:

Interface Required	Transceiver Type	Running Version	New Version	Upg Required	Reload
fc6/18	CISCO-ACCELINK	1.0	1.1	yes	yes
fc7/3	CISCO-ACCELINK	1.0	1.1	yes	yes

Transceiver firmware upgrade is a disruptive operation and all interfaces, including those interfaces that do not need upgrading in the respective line card(s), will be shutdown during the process. This will take approximately 00 hrs 08 mins to complete.

Any module with transceivers upgraded will be reloaded after the upgrade is finished.

Do you want to proceed (y/n)?[n]: **y**

Proceeding with upgrade. Do not attempt any operations on the line card(s) where transceiver modules are undergoing upgrade.

Upgrading transceiver firmware on interface fc6/18.

Firmware upgrade of transceiver on interface fc6/18 is successful.

Upgrading transceiver firmware on interface fc7/3.

Firmware upgrade of transceiver on interface fc7/3 is successful.

Bringing up the interfaces after the upgrade.

Transceiver firmware upgrade status is as follows:

Interface	Transceiver Type	Old Version	Current Version	Result
fc6/18	CISCO-ACCELINK	1.0	1.1	Success
fc7/3	CISCO-ACCELINK	1.0	1.1	Success

Reloading module(s) [6, 7] to complete the upgrade process. Please check the module status using `show module` command.

2024 Jan 15 04:21:55 Transceiver firmware upgrade completed  
switch#

To update transceiver firmware on all supported modules in a Director switch, use the **install transceiver** command without the **module** keyword.

#### Example: Updating the transceiver firmware on all supported transceivers in a Cisco MDS 9700 Series Switch

```
switch# install transceiver nxos-transceiver-firmware.mds.9.4.1a.bin
```

Locking current install transceiver session

2024 Jan 15 02:27:10 Starting transceiver firmware upgrade image file /bootflash/nxos-transceiver-firmware.mds.9.4.1a.bin

2024 Jan 15 02:27:10 Extracting transceiver firmware(s) from package

357+1 records in

357+1 records out

234660 bytes (235 kB) copied, 0.00289415 s, 81.1 MB/s

Version (CISCO-ACCELINK) : 1.1

Version (CISCO-FINISAR) : 1.1

Upgrading transceivers on module(s): [1, 8, 18]

Collecting interface configuration and transceiver information, please wait.

Transceivers will be upgraded according to following table:

Interface	Transceiver Type	Running Version	New Version	Upg Required	Reload
fc1/1	CISCO-FINISAR	0.126	1.1	yes	yes
fc1/15	CISCO-ACCELINK	0.188	1.1	yes	yes
fc8/4	CISCO-ACCELINK	0.188	1.1	yes	yes
fc18/31	CISCO-FINISAR	0.126	1.1	yes	yes

Transceiver firmware upgrade is a disruptive operation and all interfaces, including those interfaces that do not need upgrading in the respective line card(s), will be shutdown during the process. This will take approximately 00 hrs 15 mins to complete.

Any module with transceivers upgraded will be reloaded after the upgrade is finished.

-----  
Do you want to proceed (y/n)?[n]: **y**

Proceeding with upgrade. Do not attempt any operations on the line card(s) where transceiver modules are undergoing upgrade.

Upgrading transceiver firmware on interface fc1/1.  
Firmware upgrade of transceiver on interface fc1/1 is successful.

Upgrading transceiver firmware on interface fc1/15.  
Firmware upgrade of transceiver on interface fc1/15 is successful.

Upgrading transceiver firmware on interface fc8/4.  
Firmware upgrade of transceiver on interface fc8/4 is successful.

Upgrading transceiver firmware on interface fc18/31.  
Firmware upgrade of transceiver on interface fc18/31 is successful.

Bringing up the interfaces after the upgrade.

Transceiver firmware upgrade status is as follows:

Interface	Transceiver Type	Old Version	Current Version	Result
fc1/1	CISCO-FINISAR	0.126	1.1	Success
fc1/15	CISCO-ACCELINK	0.188	1.1	Success
fc8/4	CISCO-ACCELINK	0.188	1.1	Success
fc18/31	CISCO-FINISAR	0.126	1.1	Success

Reloading module(s) [1, 8, 18] to complete the upgrade process. Please check the module status using `show module` command.

2024 Jan 15 02:44:16 Transceiver firmware upgrade completed  
switch#

## Updating the Transceiver firmware on a Fabric Switch

switch# **install transceiver bootflash:nxos-transceiver-firmware.mds.9.4.1a.bin**

Locking current install transceiver session

2024 Jan 15 01:57:26 Starting transceiver firmware upgrade image file /bootflash/nxos-transceiver-firmware.mds.9.4.1a.bin



2024 Jan 15 01:57:26 Extracting transceiver firmware(s) from package  
357+1 records in  
357+1 records out  
234649 bytes (235 kB, 229 KiB) copied, 0.00224521 s, 105 MB/s

Version (CISCO-ACCELINK) : 1.1  
Version (CISCO-FINISAR) : 1.1

Upgrading transceivers on module(s): [1]  
Collecting interface configuration and transceiver information, please wait.  
Transceivers will be upgraded according to following table:

Interface Required	Transceiver Type	Running Version	New Version	Upg Required	Reload
fc1/18	CISCO-ACCELINK	1.0	1.1	yes	yes
fc1/19	CISCO-FINISAR	0.101	1.1	yes	yes

Transceiver firmware upgrade is a disruptive operation and all interfaces, including those interfaces that do not need upgrading in the switch, will be shutdown during the process. This will take approximately 00 hrs 04 mins to complete.

This switch will be reloaded after the upgrade is finished.

Do you want to proceed (y/n)?[n]: **y**

Proceeding with upgrade. Do not attempt any operations on the switch where transceiver modules are undergoing upgrade.

Upgrading transceiver firmware on interface fc1/18.  
Firmware upgrade of transceiver on interface fc1/18 is successful.

Upgrading transceiver firmware on interface fc1/19.  
Firmware upgrade of transceiver on interface fc1/19 is successful.

Bringing up the interfaces after the upgrade.

Transceiver firmware upgrade status is as follows:

Interface	Transceiver Type	Old Version	Current Version	Result
fc1/18	CISCO-ACCELINK	1.0	1.1	Success
fc1/19	CISCO-FINISAR	0.101	1.1	Success

Reloading this switch to complete the upgrade process

switch#

**Example: upgrading transceiver firmware when the transceiver power control feature is enabled.**

switch# **install transceiver bootflash:nxos-transceiver-firmware.mds.9.4.2.bin module 7**

Locking current install transceiver session

2024 May 06 14:32:53 Starting transceiver firmware upgrade image file /bootflash/nxos-transceiver-firmware.mds.9.4.2.bin

2024 May 06 14:32:53 Extracting transceiver firmware(s) from package

613+1 records in

613+1 records out

402271 bytes (402 kB, 393 KiB) copied, 0.00298808 s, 135 MB/s

Version (CISCO-ACCELINK, DS-SFP-FC64G-SW) : 1.2

Version (CISCO-FINISAR, DS-SFP-FC64G-SW) : 1.1

Version (CISCO-INNOLIGHT, DS-SFP-FC64G-LW) : 0.24

Upgrading transceivers on module(s): [7]

Transceiver power-control is ON, which will be turned OFF to perform firmware upgrade.

Do you want to proceed (y/n)?[n]: y

Collecting interface configuration and transceiver information, please wait.

Transceivers will be upgraded according to following table:

Interface Required	Transceiver Type	Running Version	New Version	Upg Required	Reload
fc7/1	CISCO-ACCELINK	1.1	1.2	yes	yes
fc7/17	CISCO-INNOLIGHT	0.23	0.24	yes	yes

Transceiver firmware upgrade is a disruptive operation and all interfaces, including those interfaces that do not need

upgrading in the respective line card(s), will be shutdown during the process. This will take approximately 00 hrs 09

mins to complete.

Any module with transceivers upgraded will be reloaded after the upgrade is finished.

Do you want to proceed (y/n)?[n]: y

Proceeding with upgrade. Do not attempt any operations on the line card(s) where transceiver modules are undergoing

upgrade.

Upgrading transceiver firmware on interface fc7/1.

Firmware upgrade of transceiver on interface fc7/1 is successful.

Upgrading transceiver firmware on interface fc7/17.

Firmware upgrade of transceiver on interface fc7/17 is successful.

Bringing up the interfaces after the upgrade.

Transceiver firmware upgrade status is as follows:

Interface	Transceiver Type	Old Version	Current Version	Result
-----------	------------------	-------------	-----------------	--------

Module	Current Version	Target Version	Status
fc7/1	CISCO-ACCELINK 1.1	1.2	Success
fc7/17	CISCO-INNOLIGHT 0.23	0.24	Success

Reloading module(s) [7] to complete the upgrade process. Please check the module status using `show module` command.

### Cleaning a Previously Terminated Upgrade

Accessing transceivers during an upgrade can cause permanent damage to them. To prevent any damage, only one upgrade session is permitted at a time. The following message is displayed when an attempt is made to start parallel upgrades.

```
switch# install transceiver bootflash:nxos-transceiver-firmware.mds.9.4.1a.bin
Already one active install transceiver session is in progress. Running parallel install
transceiver session(s) are not allowed.
If you want to re-run install transceiver due to previously aborted session(if any), please
run 'install transceiver clean' first to do clean up and try running install transceiver
again.
```

switch#  
If there are no parallel upgrade sessions are running, and the above message is from a previously terminated upgrade, use the **install transceiver clean** command to clear the session and run the install command again.

#### Example: Cleaning previously terminated transceiver upgrade

```
switch# install transceiver clean
```

**Warning:** Running this command clears the lock on any ongoing upgrade. The original upgrade process is not stopped and a subsequent upgrade will then be allowed, making the upgrade process likely to fail and cause transceiver damage. It is advised to use the **install transceiver clean** command only after an upgrade fails or terminates.

If an upgrade is terminated, wait for a few minutes for any ongoing upgrade to complete before attempting again. The approximate time required to complete each transceiver install session is displayed in the banner text before any upgrade process starts.

-----  
Transceiver firmware upgrade is a disruptive operation and all interfaces, including those interfaces that do not need upgrading in the respective line card(s), will be shutdown during the process. This will take approximately **00 hrs 15 mins** to complete.

Any module with transceivers upgraded will be reloaded after the upgrade is finished.  
-----

## Resolved Issues

### Severity 3 (Moderate) Issues

Bug ID	Headline	Transceiver PID Transceiver type	Known Affected Manufacturer's part number Firmware Versions
<a href="#">CSCwe84668</a>	ISLs at 64 Gbps speed go to notConnected state sometimes after several flaps	DS-SFP-FC64G-SW CISCO-ACCELINK	NA 1.1 and earlier
		DS-SFP-FC64G-SW CISCO-FINISAR	FTLF8564D1xxx-xx 1.1 and earlier

## Open Issues

There are no open issues in Cisco MDS 9000 Series Transceiver Firmware Release 9.4(2).

## Legal Information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2024 Cisco Systems, Inc. All rights reserved.