



Release Notes for Cisco Aironet 1800S Active Sensor, Cisco Wireless Release 2.3.4.0

First Published: 2022-10-09

About the Release Notes

This release notes document describes what is new or changed in this release. The document is updated as needed to provide information about new features, caveats, potential software deferrals, and related documents for the Cisco Aironet 1800S Active Sensor for this release.

We recommend that you view the field notices for this release to check whether your software or hardware platforms are affected. If you have an account on Cisco.com, you can find the field notices at http://www.cisco.com/en/US/customer/support/tsd_products_field_notice_summary.html.

However, if you do not have a Cisco.com account, you can find the field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

Overview of Cisco Aironet 1800S Active Sensor

The Cisco Aironet 1800S Active Sensor is a part of the Cisco DNA Center Assurance solution. The DNA Center Assurance platform has three components—Wireless Performance Analytics, Real-time Client Troubleshooting, and Proactive Health Assessment.

In this document, the term *Network Sensor* or *sensor* refers to the Cisco Aironet 1800S Active Sensor.

The Cisco Aironet 1800S Active Sensor is an 802.11a/b/g/n/ac (Wave 2) sensor with internal antennas. The sensor can be mounted, in a vertical orientation, on a wall or a desk, and supports 2x2:2 SS. The sensor is capable of joining an infrastructure access point as a client. The sensor can be used to monitor, measure, and troubleshoot a wireless network's overall performance.

For more information about the sensor, including mounting instructions and limited troubleshooting procedures, setup, and configuration, see the [Cisco Aironet 1800S Active Sensor Getting Started Guide](#).

What's New in Release 2.3.4.0

There are no new features that are introduced in this release.

For more information about updates in this release, see the Caveats section in this document.

Limitations and Caveats

This section provides information about known limitations and caveats relating to this release.

Known Limitations

- The sensor fails to detect broadcasted beacons by other APs while scanning its RF environment. However, this behavior occurs intermittently with low probability. It does not associate with the target SSID when it cannot see the beacons and skips the test. The DNAC logs show the detection success rates. For more information, see [CSCwa25257](#).
- **Problem** If you enable P2P blocking on the controller, or set it to forward upstream, you might observe IP Service-Level Agreement (SLA) test failures on the Cisco DNA Center sensor dashboard.
Solution To avoid this issue, disable P2P on the controller.
- **Problem** If the sensor runs on Cisco wireless software, such as Cisco Wireless Release 8.5 that supports Cisco IOS-based (Wave 1) APs, you might experience IP SLA test failure.
Solution To avoid this issue, disable the IP SLA test for Cisco Wave 1 APs.

Caveats

Caveats describe unexpected behavior in the Cisco Wireless Network Sensor software. Severity 1 caveats are the most serious, while Severity 2 caveats are less severe.

The Open Caveats and Resolved Caveats sections list the caveats for this release.

Each caveat contains the following information:

- **Identifier:** Each caveat is assigned a unique identifier (ID) with a pattern of CSCxxNNNNN, where x is any letter (a-z), and N is any number (0-9). Cisco documentation such as Security Advisories, Field Notices and other Cisco support documents frequently refer to these caveat IDs. Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific caveat.
- **Description:** A description is a brief of the issue observed when the caveat occurs.

Cisco Bug Search Tool

The [Cisco Bug Search Tool](#) (BST), the online successor to the Bug Toolkit, is designed to improve network risk management and device troubleshooting effectiveness. The BST allows partners and customers to search for software bugs based on product, release, and keyword and aggregates vital data, such as bug details, product, and version. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

For more information about using the [Cisco Bug Search Tool](#) effectively, including setting email alerts for bugs, filtering bugs, and saving bugs and searches, see the [Bug Search Tool Help & FAQ](#) page.

You can access the listed bugs through the BST. This web-based tool provides you access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in the Cisco Wireless Network Sensor software and other Cisco hardware and software products.

Click the Caveat Identifier number in the table. The corresponding BST page gets displayed with the details of the bug.



Note If you are not logged in, you will be redirected to a **Log In** page where you need to enter your registered Cisco.com username and password to log in. If you do not have a Cisco.com account, you can [register](#) for one.

If the defect that you have selected cannot be displayed, this may be due to one or more of the following reasons:

- The defect number does not exist
- The defect does not have a customer-visible description yet
- The defect is marked Cisco Confidential

Open Caveats

There are no open caveats in Release 2.3.4.0.

Resolved Caveats

Table 1: Resolved Caveats for Release 2.3.4.0

Identifier	Headline
CSCwb23176	Cisco 1800S sensors become unreachable and fail to auto register with DNAC through PnP flow
CSCwb55632	Cisco 1800S AP's fail to toggle WMM values when executing sensor tests
CSCwb58494	Cisco 1800S sensor PnP discovery using DHCP method failed
CSCwb58505	Cisco 1800S sensor PnP discovery using DNS method fail
CSCwb62284	Sensor 'show arp' and 'show ip route' display wrong info
CSCwb90518	Sensor sending continuous IPSLA requests to DNAC before test configs are pushed to sensor

Service and Support

For all support-related information, see <http://www.cisco.com/c/en/us/support/index.html>.

Related Documentation

- [Cisco Aironet 1800S Active Sensor Getting Started Guide](#)
- [Cisco Aironet Sensor Deployment Guide](#)

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2022 Cisco Systems, Inc. All rights reserved.