

# Cisco Meeting Server **High** CVE-2018-0262



**CVE ID :** cisco-sa-20180502-cms-cx  
**Published :** 2018-05-02 16:00  
**Version :** Final  
**CVSS Score :** [8.8](#)  
**Workarounds :** No workarounds available  
**Cisco ID :** [CSCvg76469](#)

[CVE-2018-0262](#)

**Summary:** Cisco Meeting Server versions 1.0 through 1.0.1 are vulnerable to a Denial of Service (DoS) attack via a crafted SIP INVITE message.

## Details

Cisco Meeting Server

Cisco Meeting Server versions 1.0 through 1.0.1 are vulnerable to a Denial of Service (DoS) attack via a crafted SIP INVITE message.

The vulnerability is caused by a buffer overflow in the SIP INVITE message processing logic. An attacker can exploit this by sending a specially crafted SIP INVITE message that causes a buffer overflow, leading to a Denial of Service (DoS) attack.

## Traversal Using Relay

NAT/TURN traversal using relay is supported in Cisco Meeting Server.

Security: TLS is supported for SIP signaling. TURN is supported for media traversal.

For more information, see the Cisco Security Advisory for CVE-2018-0262.

For more information, see the Cisco Security Advisory for CVE-2018-0262.

For more information, see the Cisco Security Advisory for CVE-2018-0262.  
<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180502-cms-cx>

## References

For more information, see the Cisco Security Advisory for CVE-2018-0262.

## ❖ ®ã❖,ã,«è£½ă”❖

ã❖”ã❖®è,,†ă½±æ€šã❖™ã❖CMS ã,½ăf•ăf^ã,|ã,šã,ç ãf^ãf^ãf^ã,¹ 2.2.11

ã,^ã,šã%ã❖ã,^ã®ÿè;CEã❖—ã❖|ã❖,,ã,« Cisco Meeting Serveri¼^CMSi¼%ãAcano X

ã,•ăf^ãf^ã,° ãf—ãf©ãffãf^ãf•ã,©ãf^ãf ã❖«ă½±éÿ;ã,^ã,žã❖^ã❖¾ã❖™ã€,

ç®;ç❖†è€...ã❖™ CLI ã❖® version

ã,¾ăfžăf^ãf%ã,^ã½;ç”ã❖—ã❖|ã❖ã❖ăf†ăf❖ã,ãã,¹ã❖šã®ÿè;CEã❖•ã,CEã❖|ã❖,,ã,« CMS

ã,½ăf•ăf^ã,|ã,šã,ç ãf^ãf^ãf^ã,¹ã,^ã^ã^ã^ãšã❖❖ã❖¾ã❖™ã€,æ¬;ã❖«ã❖CMS

ã,½ăf•ăf^ã,|ã,šã,ç ãf^ãf^ãf^ã,¹ 2.2.11

ã,^ã®ÿè;CEã❖—ã❖|ã❖,,ã,«ăf†ăf❖ã,ãã,¹ã❖®ã,¾ăfžăf^ãf%ã†°ãš>ă¾ã,^çã°ã❖—ã❖¾ã❖™ã€,

<#root>

system>

version

2\_2\_11

TURN ã,µf^ãf❖ã❖§ TLS

ã,^ã®ÿè;CEã❖™ã,«ã,^ã❖†ã❖«è”ã®šã❖™ã,«ã❖«ã❖™ã€ã,¾ăf^ãf•ã,£ã,®ăf¥ăf-ăf^ã,•ăfšăf^ã❖«

**turn tls ã,¾ăfžăf^ãf%ã❖” turn certs**

ã,¾ăfžăf^ãf%ã❖CEã”ãce”ã❖—ã❖|ã❖,,ã,«ă½...è|❖ã❖CEã❖,ã,šã❖¾ã❖™ã€,TURN

ã,µf^ãf❖ã❖®ãf;ã,ãăf^ãfœăf^ãf%ãç®;ç❖†ăf—ăfã,»ăffã,µi¼^MMPi¼%ã❖® TLS

è”ã®šã❖™ã€ç®;ç❖†è€...ã❖CE MMP ã,¾ăf^ã,½ăf^ãf«ã❖§ turn

ã,¾ăfžăf^ãf%ã,^ã®ÿè;CEã❖—ã❖|çç°èã❖ã❖šã❖❖ã❖¾ã❖™ã€,

æ¬;ã❖«ã❖TURN ã,µăf^ãf❖ã❖« TLS ã❖CEè”ã®šã❖•ã,CEã❖ÿã,^ã,¹ăftăf ã❖šã❖® turn

ã,¾ăfžăf^ãf%ã❖®ă†°ãš>ă¾ã,^çã°ã❖—ã❖¾ã❖™ã€,

<#root>

cms >

turn

Enabled: true

Username: cisco

Password: 1234

Realm: nicedet.com





Teami1/4^PSIRTi1/4%ã ¨ã€æœ¬ã,ćăf%œăfã,ã,ã,¶ã,¶ãfãã«è¨~è1/4%œã•ã,Ĉã|ã„ã,è,†ã1/4±æ€Šã

ã†°ã... ,

æœ¬è,†ã1/4±æ€Šã ¨ã€ã,ã,1ã,³ã†...éf¨ãšã®ã,»ã,ãfãfãfãftã,£ãftã,1ãfãã«ã,^ã£ã|ç™ºè|ã•ã,Ĉã¾ã—ãŸã€,

## URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180502-cms-cx>

æ”¹è¨,ã±Ÿæ´

ãfãf1/4ã,ãfsãf³	èª¬æŽ	ã,»ã,¬ã,ãfšãf³	ã,1ãf†ãf1/4ã,¿ã,¹	æ—Ÿã~
1.0	ã^ã>žã...¬é¬ãfããfãf1/4ã,¹	-	Final	2018 å¹´ 5 æœ¬² æ—Ÿ

ã^©ç”¨è!ç´,,

æœ¬ã,ćăf%œăfã,ã,ã,¶ã,¶ãfãã ¨ç,¶ã¿è¨1/4ã®ã,ã®ããã—ã|ã”æãã¾ãã—ã|ãŠã,Šã€æœ¬è,ćăf%œăfã,ã,ã,¶ã,¶ãfãã®æf...ã±ãŠã,^ã³ãfããf³ã,¬ã®ã½¿ç¨¨ã«é¬ćã™ã,è²¬ã»ã®ã,€ã¾ãŸã€ã,ã,1ã,³ã ¨æœ¬ãf%œă,ãfããfããfããã®ã†...ã®¹ã,'ã°ãŠããã—ã«ã%œæ’ã—ãæœ¬ã,ćăf%œăfã,ã,ã,¶ã,¶ãfãã®è¨~è¿ã†...ã®¹ã«é¬ćã—ã|æf...ã±è...ã¿ãã® URLã,‘çœç•Ÿã—ã€ãã~ç¬ãã®è»çè1/4%œã,,æ,è¨³ã,'æ¬½ãã—ãŸã’ã^ã€ã½”ç¾ã¾Ĉç®içãã”ã®ãf%œă,ãfããfããfããã®æf...ã±ã ¨ã€ã,ã,1ã,³è£½ã”ã®ã,¨ãfããf%œăf|ãf1/4ã,¶ã,ã¾ã±ã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。