

# High Cisco IP Phone 6800-7800-8800 Session Initiation Protocol Denial of Service (DoS) Vulnerability



**Severity:** High  
**Product:** Cisco IP Phone 6800-7800-8800  
**Version:** Session Initiation Protocol  
**CVSS:** 7.5  
**Workarounds:** No workarounds available  
**Cisco ID:** CSCvi24718

[CVE-2018-0316](#)

**Summary:** A Denial of Service (DoS) vulnerability exists in Cisco IP Phone 6800-7800-8800. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) condition on the affected device.

**Impact:** Denial of Service (DoS)

**Description:** A Denial of Service (DoS) vulnerability exists in Cisco IP Phone 6800-7800-8800. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) condition on the affected device. The vulnerability is caused by a buffer overflow in the Session Initiation Protocol (SIP) processing logic.

**Workarounds:** No workarounds are available for this vulnerability.

**References:** [Cisco Security Advisory: Cisco IP Phone 6800-7800-8800 Session Initiation Protocol Denial of Service \(DoS\) Vulnerability](#)

**Additional Information:** This vulnerability affects Cisco IP Phone models 6800, 7800, and 8800. The vulnerability is caused by a buffer overflow in the Session Initiation Protocol (SIP) processing logic.

**Additional Information:** This vulnerability affects Cisco IP Phone models 6800, 7800, and 8800. The vulnerability is caused by a buffer overflow in the Session Initiation Protocol (SIP) processing logic. For more information, see the [Cisco Security Advisory: Cisco IP Phone 6800-7800-8800 Session Initiation Protocol Denial of Service \(DoS\) Vulnerability](https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180606-multiplatform-sip).

# è©²å¹/²“è£¹/²å”

è,†å¹/²±æ€§šã®ã,ã,«è£¹/²å”

ãfžãf«ãf—ãf©ãffãf^ãf•ã,©ãf¹/²ãf ãf•ã,ãf¹/²ãf ã,|ã,šã,çæè¼%ã Cisco IP Phone  
6800ã€7800ã€ãšã,^ã³ 8800 ã,ãfªãf¹/²ã,°ã€ã€ãfªãf¹/²ã,¹ 11.1(2)

ã,^ã,šã%ã®ã®ãfžãf«ãf—ãf©ãffãf^ãf•ã,©ãf¹/²ãf

ãf•ã,ãf¹/²ãf ã,|ã,šã,çã,â®ÿè;ã€—ã|ã,ã,ã,ã^ã€ã“ã®è,,†å¹/²±æ€§šã®å¹/²±éÿã,â

è,†å¹/²±æ€§šã,â«ã,“ãšã,,ãªã,,ã“ã”ã€çç°èªã•ã,ã€ÿè¹/²å”

ã“ã®ã,çãf%ããfã,ã,ã,ãfªã®è,,†å¹/²±æ€§šã®ã,ã,«è£¹/²å”ã,»ã,ã,ãfšãf³ã«è¼%ã•ã

## ãžéç-

ã“ã®è,,†å¹/²±æ€§šã«ã³ã†|ã™ã,ãžéç-ã-ã,ã,šã¾ãã,ã,ã€,

## ã;®æ£æ,^ãçã,¹/²ãf•ãf^ã,|ã,šã,ç

ã,ã,ã,ã,ã-ã“ã®ã,çãf%ããfã,ã,ã,ãfªã«è¼%ã•ã,ã€ÿè,,†å¹/²±æ€§šã«ã³ã†|ã™ã,ç,ã,  
ãfãf¹/²ã,ãfšãf³ã”ãf•ã,£ãf¹/²ãfãf£

ã,»ãffãf^ã«ã³ã-ã|ã®ãçã”ãªã,šã¾ãã™ã€ã,ã,ã®ã®,^ãtãªã,¹/²ãf•ãf^ã,|ã,šã,  
<https://www.cisco.com/c/en/us/products/end-user-license-agreement.html>

ã«è¼%ã®ã,ã,ã,ã,ã®ã,¹/²ãf•ãf^ã,|ã,šã,çãf©ã,ã,»ãf³ã,ã®æçé...ã«ã¾ãtã“ã”ã

ã¾ãÿã€ãšã®çæš~ã€ã,¹/²ãf•ãf^ã,|ã,šã,çã,ãfã,|ãf³ãfãf¹/²ãf%ãšãã,ã®ã-ã€ã,  
ã,çãffãf—ã,°ãf-ãf¹/²ãf%ãšã™ã€ç,,ã,ã,ã,ã,»ã,ãfªãfãfã,£ã,¹/²ãf•ãf^ã,|ã,šã,ç

ã,çãffãf—ãfªãf¹/²ãf^ã«ã,^ã£ã|ã€ãšã®çæš~ã«æ-°ã-ã,,ã,¹/²ãf•ãf^ã,|ã,šã,ç

ãf©ã,ã,»ãf³ã,ã€è:¹/²ãšã,¹/²ãf•ãf^ã,|ã,šã,çãf•ã,£ãf¹/²ãfãf£

ã,»ãffãf^ã€ã¾ãÿã-ãfã,ãf£ãf¹/²ãfªãfã,ãfšãf³

ã,çãffãf—ã,°ãf-ãf¹/²ãf%ã«ã³ã†|ã™ã,ã€”©é™ã€ã€ã~ã,žã•ã,ã€ã,ã“ã”ã-ã-ã,ã,šã¾ãã

ã,¹/²ãf•ãf^ã,ã,šã,çã®ã,çãffãf—ã,°ãf-ãf¹/²ãf%ã,æœœè”žã™ã,«éšã«ã-ã€[ã,ã,ã,ã,ã,ã,  
Security Advisories and Alerts]¼%

ãfšãf¹/²ã,ãšã...æ%ããšããã,ã,ã,ã,ã,ã,³è£¹/²å”ã®ã,çãf%ããfã,ã,ã,ãfªã,â®šæœÿçš,ã«ã,ç,  
ã,¹/²ãfªãfªf¹/²ã,ãfšãf³ã,çç°èªã-ã|ããããã•ã,,ã€,

ã,,ãšã,ã€ã®ã^ã,,ã€ã,çãffãf—ã,°ãf-ãf¹/²ãf%ã™ã,ãfªãfã,ã,ã,ã,ã«ã^ãtãªãªãfãfã  
Technical Assistance

Center¼^TAC]¼%ã,,ã-ããã-ãÿç’,ã-ã|ã,,ã,ãfãf³ãfãfšãf³ã,ãf—ãfãfã,ãf£ãf¹/²ã

ã,ãf¹/²ãf“ã,ãÿç’,ã,ã





## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。