End-of-Sale and End-of-Life Announcement for the Cisco Prisma II Optical Passives (select PIDs only)

EOL12262

Cisco announces the end-of-sale and end-of-life dates for the Cisco Prisma II Optical Passives (select PIDs only). The last day to order the affected product(s) is August 3, 2018. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco Prisma II Optical Passives (select PIDs only)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 2, 2018
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 3, 2018
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 1, 2018
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 3, 2019
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 3, 2019
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 29, 2022
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete **. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	August 31, 2023

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030179	LGX-DWDM-MXDX 8CH 100G ITU25-32 DTP-UG-EXP-LA	1030017	LGX-DWDM-MXDX 1X16 ITU2540 DTP-UG-EXP-LA	-
1030180	LGX-DWDM-MXDX 8CH 100G ITU33-40 DTP-UG-EXP-LA	1030017	LGX-DWDM-MXDX 1X16 ITU2540 DTP-UG-EXP-LA	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030305	Cas-S-CWDM-MXDX 8CH Type B DTP-Express-SA-NC (47-61)	4007298	(CAS-MXDX-1x8-20nm-900-NC-14701610)CWDM Mx/DMx, 1x8, 1470-1610	-
1030306	Cas-S-CWDM-MXDX 8CH Type C DTP-Express-SA-NC (43-51, 57-61)	There is currently no replacement product available for this product.	-	-
254602	(LL-BWDM-RBP-S)BWDM Mx/DMx, R/B/P, Sgl	There is currently no replacement product available for this product.	-	-
254607	(LL-BWDM-RBP-8W)BWDM Mx/DMx, R/B NC/BC Cmbnr, 8CH, SA, Wide	There is currently no replacement product available for this product.	-	-
4000690	(JMPR-9SS-2-S-LP-LP-015)Jmpr, SM Sx, 2mm, Std, LP-LP, 15m	There is currently no replacement product available for this product.	-	-
4000802	(JMPR-6MD-3-S-LP-MP-003)Jmpr, 62.5MM Dx, 3mm, Std, LP-MP, 3m	There is currently no replacement product available for this product.	-	-
4005610	DWDM Mx/DMx, 4CH, ITU17, 19, 21, 23, LGX, SA	There is currently no replacement product available for this product.	-	-
4006682	DWDM Mx/DMx, Blue 1x8, (ITU45-59, 200GHz, SA, TPs, 2slot)	1030031	LGX-DWDM MXDX 1X20 ITU 40-59 DTP-UG-EXP-LA	-
4009666	(JMPR-9SS-2-S-LA-LA-005)Jmpr, SM Sx, 2mm, Std, LA-LA, 5m	There is currently no replacement product available for this product.	-	-
4010859	LGX-BWDM MXDX 10Band ITU20-59 DTP SA	There is currently no replacement product available for this product.	-	-
4010860	LGX-BWDM MXDX 5Band ITU20-39 DTP SA	There is currently no replacement product available for this product.	-	-
4011485	(RM-CPLR-1RU-1X32-EVEN-SA)Opt Cplr, 1x32, 1RU, Even, SA	There is currently no replacement product available for this product.	-	-
4012465	(CAS-DWDM-200G-1X8-RED-2135-SA)DWDM Mx/DMx, 1x8R, ITU21-35, SA	OPCAS-MD20-2039-SA	CAS-DWDM-MXDX-20CH-ITU20-39-DTP-UG-EXP-SA-SC/APC all tails	-
4013019	(JMPR-9SS-2-S-LA-LA-003)Jmpr, SM Sx, 2mm, Std, LA-LA, 3m	There is currently no replacement product available for this product.	-	-
4014113	(JMPR-9SD-3-S-LP-LP-003)Jmpr, SM Dx, 3mm, Std, LP-LP, 3m	There is currently no replacement product available for this product.	-	-
4021219DEM	CAS-DMUX-1X4-OBAND-AD-SC/APC W/UPG	4021219	CAS-DMUX-1X4-OBAND-AD-SA, 1x4 Dnstrm Out Plnt, Ch A/B/C/D	-
4027301	MICROVAM-MXDX-1X4-OBAND-AD-SA-UPG, 1x4 Dnstrm Hub, A/B/C/D, ADC	There is currently no replacement product available for this product.	-	-
4027302	MICROVAM-MXDX-1X2-OBAND-AB-SA-UPG, 1x4 Dnstrm Hub, A/B, ADC Hsg	There is currently no replacement product available for this product.	-	-
4027303	MICROVAM-MXDX-1X2-OBAND-CD-SA, UPG, 1x2 Dnstrm Hub, C/D, ADC Hsg	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4028569	LGX-COUPLER-2X2-EVEN-QUAD-SA (1 slot, OLT VOLT port at back)	There is currently no replacement product available for this product.	-	-
4029427	Service Cbl, 32 Fiber, 4 Ribbon Cbl, 4 MPO Conn, 100Ft	There is currently no replacement product available for this product.	-	-
4030667	JMPR-8SRC-J-S-MA-MA-NA-001(MPO to MPO Jumper 1 meter)	There is currently no replacement product available for this product.	-	-
4033333	Opt Add/Drop Mux, Fltr, DWDM ITU18, SA	There is currently no replacement product available for this product.	-	-
4033334	LGX-MXDX-1X8-20NM-LA-1470-1610/EXP-DTP (CWDM 1 slot LC/APC)	There is currently no replacement product available for this product.	-	-
4033335	LGX-MXDX-1X8-20NM-LP-1470-1610/EXP-DTP (CWDM 1 slot LC/UPC)	There is currently no replacement product available for this product.	-	-
4036782	LGX-DWDM-MXDX 8CH 100G 16-23 SA DTP (2 Slot w/ Test Point)	There is currently no replacement product available for this product.	-	-
4036783	LGX-DWDM-MXDX 8CH 100G 25-32 SC/APC (2 Slot w/ Test Point)	There is currently no replacement product available for this product.	-	-
4036784	LGX-DWDM-MXDX 8CH 100G 34-41 SC/APC (2 Slot w/ Test Point)	OPLGX-MD40-2059-LQ	Dual-wide LGX-MXDX-40 ch-ITU 20-59 using quad LC/APC	-
4036785	LGX-DWDM-MXDX 8CH 100G 43-50 SC/APC (2 Slot w/ Test Point)	There is currently no replacement product available for this product.	-	-
4036786	LGX-DWDM-MXDX 8CH 100G 52-59 SC/APC (2 Slot w/ Test Point)	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
4037361	LGX-BWDM-1X2-2035-3651-SA	There is currently no replacement product available for this product.	-	-
4037362	LGX-BWDM-1X2-2027-2835-SA	There is currently no replacement product available for this product.	-	-
4037363	LGX-BWDM-1X2-3643-4451-SA	There is currently no replacement product available for this product.	-	-
4037365	LGX-BWDM-MXDX 5Band ITU40-59, DTP SA	There is currently no replacement product available for this product.	-	-
4038838	LGX, BWDM, FTTX, 1310/1490/1550, Quad LC/APC	There is currently no replacement product available for this product.	-	-
4040459	CAS-BWDM-13101490/1550-SU/LA/SA(15M SU/LA, 15M Jumper SA)	There is currently no replacement product available for this product.	-	-
4040682	Service Cable, 4 MPO Conn, 32 Fbr SC/APC-25 Ft	There is currently no replacement product available for this product.	-	-
4040743	LGX-BWDM 5Band 8SKIP0 ITU20-59 SC/APC	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4042467	CAS-DWDM-MXDX 8CH ABCDEFGH LRMW SA DTP	There is currently no replacement product available for this product.	-	-
4044239	LGX-10Band-4SKIP0-2059-DTP-LC/APC	There is currently no replacement product available for this product.	-	-
4044240	LGX-5Band-4SKIP0-2039-DTP-EXP-LC/APC	There is currently no replacement product available for this product.	-	-
4044241	LGX-5Band-4SKIP0-4059-DTP-EXP-LC/APC	There is currently no replacement product available for this product.	-	-
591528	Opt Cplr, 1x2 Fused, 85/15, Unconnectorized	There is currently no replacement product available for this product.	-	-
591529	Opt Cplr, 1x2 Fused, 80/20, Unconnectorized	There is currently no replacement product available for this product.	-	-
591530	Opt Cplr, 1x2 Fused, 75/25, Unconnectorized	There is currently no replacement product available for this product.	-	-
713975	Opt Cplr, 1x10 Fused in LGX Module, Even, W/B, SA	There is currently no replacement product available for this product.	-	-
739636	Jmpr, SA-SA, 1.5m	There is currently no replacement product available for this product.	-	-
739665	Opt Cplr, 2x2, Dual Window, 50/50, LGX, SA	There is currently no replacement product available for this product.	-	-
739776	Service Cbl, 4Fiber, SA, 60ft	There is currently no replacement product available for this product.	-	-
739777	Service Cbl, 4Fiber, SA, 100ft	There is currently no replacement product available for this product.	-	-
739778	Service Cbl, 6Fiber, SA, 60ft	There is currently no replacement product available for this product.	-	-
739779	Service Cbl, 6Fiber, SA, 100ft	There is currently no replacement product available for this product.	-	-
739780	Service Cbl, 8Fiber, SA, 60ft	There is currently no replacement product available for this product.	-	-
739781	Service Cbl, 8Fiber, SA, 100ft	There is currently no replacement product available for this product.	-	-

Product Migration Options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:
https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Prisma II Optical Passives (select PIDs only) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale

in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: https://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:
https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:
https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

**For more information about the Cisco Product Warranties, go to:
https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
https://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
https://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.