

# End-of-Sale and End-of-Life Announcement for the Cisco Unified SIP Proxy v8 Legacy License Offers



# Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	4
For more information	4

## Overview

### EOL13294

Cisco announces the end-of-sale and end-of-life dates for the Cisco Unified SIP Proxy v8 Legacy License Offers. The last day to order the affected product(s) is May 29, 2020. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Customers should note that Cisco Unified SIP Proxy (CUSP) version 8.x software is now End-of-Life (see EOL10779). Customers interested in using the current CUSP release should consider purchasing licenses using the L-CUSP top level part ID.

## End-of-life milestones

**Table 1.** End-of-Life Milestones and Dates for the Cisco Unified SIP Proxy v8 Legacy License Offers

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 29, 2019
<b>End-of-Sale Date License</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 29, 2020
<b>Last Ship Date License</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 27, 2020

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

## Product part numbers

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
L-FL-CUSP-100=	CUSP Feature License for 100 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-10U100=	CUSP Upgrade License for 10 to 100 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-30=	CUSP Feature License for 30 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
L-FL-CUSP-30U100=	CUSP Upgrade License for 30 to 100 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-2=	CUSP Feature License for 2 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-10U30=	CUSP Upgrade License for 10 to 30 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-10=	CUSP Feature License for 10 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-
L-FL-CUSP-200=	CUSP Feature License for 200 SIP requests/second	CUSP10-5CPS	Cisco Unified SIP Proxy 10.x: 5 calls/sec (Smart License)	-

## Product migration options

Customers are encouraged to migrate to the Cisco Unified SIP Proxy Software 10.x

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For more information

For more information about the Cisco End-of-Life Policy, go to:

[https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)