

# End-of-Sale and End-of-Life Announcement for the Cisco Prisma II Full Height Chassis and modules

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	7
For more information	8

## Overview

### EOL14560

Cisco announces the end-of-sale and end-of-life dates for the Cisco Prisma II Full Height Chassis and modules. The last day to order the affected product(s) is May 13, 2022. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Prisma II Full Height Chassis and modules

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 12, 2021
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 13, 2022
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 11, 2022
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 13, 2023
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 13, 2023
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 8, 2026
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 31, 2027

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
714470	(P2-OPSW-SA) Opt Sw, 1310/1550nm, SA	4037229	(P2-HD-OPSW-LA) 1550HD Opt Switch, LA	-
716307	Kit, Prisma II Module Blank (Pk/6)	There is currently no replacement product available for this product.	-	-
716308	Kit, Prisma II PS Blank (Pk/6)	There is currently no replacement product available for this product.	-	-
736727	(P2-CH-R-F-28-R-AAE) Chassis, Rear Acc, 28F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736735	(P2-CH-F-F-28-R-AAE) Chassis, Frt Acc, 28F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736736	(P2-CH-F-F-28-R-AAS) Chassis, Frt Acc, 28F, 2/AC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736737	(P2-CH-F-F-28-F-AAS) Chassis, Frt Acc, 28F, 2/AC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736740	(P2-CH-F-F-28-R-DDS) Chassis, Frt Acc, 28F, 2/-48VDC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736741	(P2-CH-F-F-28-F-AAE) Chassis, Frt Acc, 28F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736743	(P2-CH-F-F-28-F-DDS) Chassis, Frt Acc, 28F, 2/-48VDC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736744	(P2-CH-F-F-56-F-DDS) Chassis, Frt Acc, 56F, 2/-48VDC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736745	(P2-CH-F-F-56-R-AAE) Chassis, Frt Acc, 56F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
736746	(P2-CH-F-F-56-R-AAS) Chassis, Frt Acc, 56F, 2/AC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736747	(P2-CH-F-F-56-F-AAE) Chassis, Frt Acc, 56F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736748	(P2-CH-F-F-56-F-AAS) Chassis, Frt Acc, 56F, 2/AC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736750	(P2-CH-F-F-56-R-DDS) Chassis, Frt Acc, 56F, 2/-48VDC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736761	(P2-CH-R-F-56-R-AAE) Chassis, Rear Acc, 56F, 2/AC Pwr, EU	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736762	(P2-CH-R-F-56-R-AAS) Chassis, Rear Acc, 56F, 2/AC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
736766	(P2-CH-R-F-56-R-DDS) Chassis, Rear Acc, 56F, 2/-48VDC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
741419	Prisma II Fan Tray, Rear Exhaust (ea)	There is currently no replacement product available for this product.	-	-
741420	Prisma II Fan Tray, Frt Exhaust (ea)	There is currently no replacement product available for this product.	-	-
741421	Prisma II Fan Kit, Fans Only (5ea)	There is currently no replacement product available for this product.	-	-
741422	Kit, Pwr Inlet, Rear Acc, AC, Std (ea)	There is currently no replacement product available for this product.	-	-
741424	Kit, Pwr Inlet, Rear Acc, DC (ea)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
741429	Kit, RF Conn, Frt or Rear Acc, F (28 ea)	There is currently no replacement product available for this product.	-	-
741982	Pwr Conn, -48VDC (12 ea)	There is currently no replacement product available for this product.	-	-
744432	Pwr Inlet, Frt Acc, AC, Std (ea)	There is currently no replacement product available for this product.	-	-
750882	Prisma II Redundancy Intfc Pnl (RIP)	There is currently no replacement product available for this product.	-	-
4008670	Faceplate, Chassis	There is currently no replacement product available for this product.	-	-
4011176	Chassis, Frt Acc, No RF, 2/DC Pwr	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4025187	(P2-ICIM-MSO) ICIM, MSO Version	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4040565	Prisma II HD, LN, RXR, SA	P2-RRX-STD	Prismall HD Dual Rev Rx, 5-300MHz, Std Input, SA	-
4008668.001.000.BA	Filtr, Replacements, Frt Acc, 1/Box	There is currently no replacement product available for this product.	-	-
4011176.003.000.AB	(P2-CH-F-X-00-R-DDS) Chassis, Frt Acc	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4011176.004.000.AB	(P2-CH-F-F-28-R-DDS) Chassis, Rear Ac	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4011176.010.000.AB	(P2-CH-F-X-00-R-DDS) (NO RF) Chassis, Frt Acc, 2/DC, NMS	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4011176.012.000.AB	(P2-CH-F-F-28-R-DDS) Chassis, Frt Acc, 28F, 2/-48VDC, NMS	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4011335.100.000.AA	P2-ICIM2, COMMUNICATION INTERFACE	4023768	(P2-XD-CH-F-ICIM) XD Chassis, F Conn, ICIM	-
4012765.001.000.AB	(P2-PS-M-A-W) PS, 90-265VAC, Std	There is currently no replacement product available for this product.	-	-
4014706.001.000.AA	Prisma II Blank Module, 24pt, 2w	There is currently no replacement product available for this product.	-	-
716307.001.000.BA	Module Blank Pnl (ea)	There is currently no replacement product available for this product.	-	-
716312.001.000.BB	(P2-PS-M-D-W) PS, - 48VDC, Std	There is currently no replacement product available for this product.	-	-
738325.201.000.AB	Prisma II Rear Exhaust Fan	There is currently no replacement product available for this product.	-	-
714470.111.000.AA	(P2-OPSW-SA) Opt Sw, 1310/1550nm, SA	4037229	(P2-HD-OPSW-LA) 1550HD Opt Switch, LA	-

## Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

[https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco Prisma II Full Height Chassis and modules through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

---

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)