



Correct Cable to Install PoE in Cisco 1941 ISR

This document is to alert the user of the AC cable to use when installing PoE in the Cisco 1941 ISRs.



Caution


If you are planning to use PoE, **do not use the AC cable that shipped with your router (PN: 37-1027-02)**, if your AC cable is the one that has the international “do not use” symbol shown in [Figure 1](#). The correct AC cable (PN: 37-1191-01) to use for PoE is shown *without* the international “do not use” symbol shown in [Figure 1](#).



Note

For complete instructions to install PoE in Cisco 1941 ISRs, go to [Installing and Upgrading Internal Modules and FRUs in Cisco 1900 Series ISRs](#).

Figure 1 AC Cable to Use When Installing PoE in Cisco 1941 ISRs



1	Wrong AC cable to use for PoE in the Cisco 1941 ISR (part number: 37-1027-02) ¹	2	Correct AC cable to use for PoE in the Cisco 1941 ISR (part number: 37-1191-01) ²
----------	---	----------	---

1. The wrong AC cable has no wire in the last wire bay.
2. The correct AC cable has the fourth black wire moved to the last wire bay.



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2010 Cisco Systems, Inc. All rights reserved.

Obtaining Documentation and Submitting a Service Request


For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS version 2.0.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Copyright © 2010 Cisco Systems, Inc. All rights reserved.

 Printed in the USA on recycled paper containing 10% postconsumer waste.