

End-of-Sale and End-of-Life Announcement for the Cisco CSP5000

Contents

Overview	3
End-of-life milestones	3
Product Part Numbers	4
Product migration options	9
For more information	9

Overview

EOL15029 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco CSP5000. The last day to order the affected product(s) is December 15, 2023. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco CSP5000

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 28, 2023
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 15, 2023
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 14, 2024
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 15, 2024
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	December 31, 2028
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 15, 2024
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 15, 2024
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 11, 2028

Milestone	Definition	Date
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2028

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Note: For CSP 5000, the last supported release of NFVIS will be version 4.9. The NFVIS 4.9 and CSP 5000 EoL milestones will match.

Product Part Numbers

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CSP-5200=	5200 1RU NFV appliance chassis spare	There is currently no replacement product available for this product.	-	-
CSP-5216	1RU NFV Platform 2 CPU-16 cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5228	1RU NFV Platform 2 CPU-28 cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5400=	5400 2RU NFV appliance chassis spare	There is currently no replacement product available for this product.	-	-
CSP-5436	2RU NFV Platform 2 CPU-36 cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5444	2RU NFV Platform 2 CPU-44 cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5444-O	2RU NFV Platform 2 CPU-44 cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5456	2RU NFV Platform 2 CPU-56 Cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-5456-O	2RU NFV Platform 2 CPU-56 Cores	L-LIC-NFVIS	Cisco NFVIS Subscription	-
CSP-BBLKD-S2	UCS C-Series M5 SFF drive blanking panel	There is currently no replacement product available for this product.	-	-
CSP-CPU-4110	2.1 GHz 4110/85W 8C/11MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CSP-CPU-5120	2.2 GHz 5120/105W 14C/19.25MB Cache/DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-6152	2.1 GHz 6152/140W 22C/30.25MB Cache/DDR4 2666MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-6154	3.0 GHz 6154/200W 18C/24.75MB Cache/DDR4 2666MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-8176	2.1 GHz 8176/165W 28C/38.50MB Cache/DDR4 2666MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-I4208	Intel 4208 2.1GHz/85W 8C/11MB DDR4 2400MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-I5220	Intel 5220 2.2GHz/125W 18C/24.75MB DCP DDR4 2666 MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-I6238	Intel 6238 2.1GHz/140W 22C/30.25MB DCP DDR4 2933 MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-I6254	Intel 6254 3.1GHz/200W 18C/24.75MB DCP DDR4 2933 MHz	There is currently no replacement product available for this product.	-	-
CSP-CPU-I8276	Intel 8276 2.2GHz/165W 28C/38.50MB DCP DDR4 2933 MHz	There is currently no replacement product available for this product.	-	-
CSP-HD12TB10K12N	1.2 TB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
CSP-MR-X16G1RS-H	16GB DDR4-2666-MHz RDIMM/PC4-21300/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CSP-MR-X16G1RT-H	16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	There is currently no replacement product available for this product.	-	-
CSP-MR-X16G1RW	16GB RDIMM SRx4 3200 (8Gb)	There is currently no replacement product available for this product.	-	-
CSP-MR-X32G2RS-H	32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
CSP-MR-X32G2RT-H	32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
CSP-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	There is currently no replacement product available for this product.	-	-
CSP-MSTOR-SD	Mini Storage Carrier for SD (holds up to 2)	There is currently no replacement product available for this product.	-	-
CSP-N2XX-AIPCI01	Intel X520 Dual Port 10Gb SFP+ Adapter	There is currently no replacement product available for this product.	-	-
CSP-N2XX-AIPCI01=	Intel X520 Dual Port 10Gb SFP+ Adapter	There is currently no replacement product available for this product.	-	-
CSP-PCI-1B-240M5	Riser 1B incl 3 PCIe slots (x8, x8, x8); all slots from CPU1	There is currently no replacement product available for this product.	-	-
CSP-PCI-2A-240M5	Riser 2A incl 3 PCIe slots (x8, x16, x16) supports GPU	There is currently no replacement product available for this product.	-	-
CSP-PCIE-ID40GF	Intel XL710 dual-port 40G QSFP+ NIC	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CSP-PCIE-IQ10GF	Intel X710 quad-port 10G SFP+ NIC	There is currently no replacement product available for this product.	-	-
CSP-PCIE-IQ10GF=	Intel X710 quad-port 10G SFP+ NIC	There is currently no replacement product available for this product.	-	-
CSP-PCIE-IRJ45	Intel i350 Quad Port 1Gb Adapter	There is currently no replacement product available for this product.	-	-
CSP-PSU1-1050W	Cisco UCS 1050W AC Power Supply for Rack Server	There is currently no replacement product available for this product.	-	-
CSP-PSU1-770W	770W AC Hot-Plug Power Supply for 1U C-Series Rack Server	There is currently no replacement product available for this product.	-	-
CSP-PSUV2-1050DC	1050W V2 -48 VDC Power Supply for CSP 2100 1RU appliance	There is currently no replacement product available for this product.	-	-
CSP-RAID-M5	Cisco 12G Modular RAID controller with 2GB cache	There is currently no replacement product available for this product.	-	-
CSP-RAID-M5HD	Cisco 12G Modular RAID controller with 4GB cache	There is currently no replacement product available for this product.	-	-
CSP-SD-64G-S	64GB SD Card for UCS Servers	There is currently no replacement product available for this product.	-	-
CSP-SD960G63X-EP	960GB 2.5in Enterprise performance 6GSATA SSD (3 DWPD)	There is currently no replacement product available for this product.	-	-
CSP-SD960GM1X-EV	960GB 2.5 inch Enterprise Value 6G SATA SSD Micron 5100	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CSP-SFP-1WLR	SFP+ for Intel X520, 10GE, LR Optical	There is currently no replacement product available for this product.	-	-
CSP-SFP-1WSR	SFP+ for Intel X520 & XL710, 10GE, SR Optical	There is currently no replacement product available for this product.	-	-
CSP-SFP-1WSR=	SFP+ for Intel X520 & XL710, 10GE, SR Optical	There is currently no replacement product available for this product.	-	-
CSP-TPM2-002	Trusted Platform Module 2.0	There is currently no replacement product available for this product.	-	-
CSP-TPM2-002=	Trusted Platform Module 2.0 for CSP 2100	There is currently no replacement product available for this product.	-	-
CSP-USBFLSHB-16GB	UCS Servers 16GB Flash USB Drive	There is currently no replacement product available for this product.	-	-
CSP-5456=	^2RU Spare NFV Platform with 56 Cores	There is currently no replacement product available for this product.	-	-
CSP-5436=	^2RUSpare NFV Platform with 36 Cores CPU	There is currently no replacement product available for this product.	-	-
CSP-5228=	^1RU Spare NFV Platform with 28 CPU Cores	There is currently no replacement product available for this product.	-	-
CSP-5216=	^1RU NFV Platform 2 CPU-16 cores Spare	There is currently no replacement product available for this product.	-	-
CSP-5444=	^2RU NFV Platform with 44 Core CPU	There is currently no replacement product available for this product.	-	-

Product migration options

Even though there are no replacement product at declaration of this End of Sale, this document will be updated with replacement product in due course with committed program(s) under development.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco CSP5000 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)