

End-of-Sale and End-of-Life Announcement for the Cisco Prisma Optical Passives (Select DWDM Products)

EOL11109

Cisco announces the end-of-sale and end-of-life dates for the Cisco Prisma Optical Passives (Select DWDM Products). The last day to order the affected product(s) is February 24, 2017. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco Prisma Optical Passives (Select DWDM Products)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	August 26, 2016
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 24, 2017
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 25, 2017
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 24, 2018
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 24, 2018
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	May 22, 2021
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	February 28, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030018	FOSC-B-BSK-Dual-CWDM-MXDX 8CH Type A DTP-EXP-SA-NC (4353, 9161)	1030304	Cas-S-CWDM-MXDX 8CH Type A DTP-Express-SA-NC (43-53, 59-61)	-
1030039	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-
1030040	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030041	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-NC	OPCAS-MD08-3643-SA	CAS-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-SC/APC all tai	-
1030042	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-NC	OPCAS-MD08-4451-SA	CAS-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-SC/APC all tai	-
1030043	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-NC	OPCAS-MD08-5259-SA	CAS-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-SC/APC all tai	-
1030044	LGX-Signal-DWDM-MXDX 4CH 100G ITU 20-23 DTP-UG-EXP-LA	1030034	LGX-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-LA	-
1030045	LGX-Signal-DWDM-MXDX 4CH 100G ITU 24-27 DTP-UG-EXP-LA	1030034	LGX-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-LA	-
1030046	LGX-Signal-DWDM-MXDX 4CH 100G ITU 28-31 DTP-UG-EXP-LA	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-
1030047	LGX-Signal-DWDM-MXDX 4CH 100G ITU 32-35 DTP-UG-EXP-LA	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-
1030048	LGX-Signal-DWDM-MXDX 4CH 100G ITU 36-39 DTP-UG-EXP-LA	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
1030049	LGX-Signal-DWDM-MXDX 4CH 100G ITU 40-43 DTP-UG-EXP-LA	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
1030050	LGX-Signal-DWDM-MXDX 4CH 100G ITU 44-47 DTP-UG-EXP-LA	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
1030051	LGX-Signal-DWDM-MXDX 4CH 100G ITU 48-51 DTP-UG-EXP-LA	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
1030052	LGX-Signal-DWDM-MXDX 4CH 100G ITU 52-55 DTP-UG-EXP-LA	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
1030053	LGX-Signal-DWDM-MXDX 4CH 100G ITU 56-59 DTP-UG-EXP-LA	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
1030054	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU20-23 DTP-UG-EXP-SA-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030055	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU24-27 DTP-UG-EXP-SA-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-
1030056	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU28-31 DTP-UG-EXP-SA-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030057	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU32-35 DTP-UG-EXP-SA-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030058	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU36-39 DTP-UG-EXP-SA-NC	OPCAS-MD08-3643-SA	CAS-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-SC/APC all tai	-
1030059	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU40-43 DTP-UG-EXP-SA-NC	OPCAS-MD08-3643-SA	CAS-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-SC/APC all tai	-
1030060	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU44-47 DTP-UG-EXP-SA-NC	OPCAS-MD08-4451-SA	CAS-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-SC/APC all tai	-
1030061	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU48-51 DTP-UG-EXP-SA-NC	OPCAS-MD08-4451-SA	CAS-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-SC/APC all tai	-
1030062	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU52-55 DTP-UG-EXP-SA-NC	OPCAS-MD08-5259-SA	CAS-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-SC/APC all tai	-
1030063	FOSC-B-BSK-Dual-DWDM-MXDX 4CH 100G ITU56-59 DTP-UG-EXP-SA-NC	OPCAS-MD08-5259-SA	CAS-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-SC/APC all tai	-
1030181	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU25-32 DTP-UG-EXP-SA-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-
1030182	FOSC-B-BSK-Dual-DWDM-MXDX 8CH 100G ITU33-40 DTP-UG-EXP-SA-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030189	FOSC-B-BSK-Dual-CWDM-MXDX 8CH Type B DTP-EXP-SA-NC (47-61)	4007298	(CAS-MXDX-1x8-20nm-900-NC-14701610) CWDM Mx/DMx, 1x8, 1470-1610	-
1030190	FOSC-B-BSK-Dual-CWDM-MXDX 8CH Type C DTP-EXP-SA-NC (4351, 5761)	1030304	Cas-S-CWDM-MXDX 8CH Type A DTP-Express-SA-NC (43-53, 59-61)	-
1030301	FOSC-B-Tray-S-CWDM-MXDX 8CH Type A DTP-Expr-SA-NC (4353,5961)	1030304	Cas-S-CWDM-MXDX 8CH Type A DTP-Express-SA-NC (43-53, 59-61)	-
1030302	FOSC-B-Tray-S-CWDM-MXDX 8CH Type B DTP-Express-SA-NC (47-61)	4007298	(CAS-MXDX-1x8-20nm-900-NC-14701610) CWDM Mx/DMx, 1x8, 1470-1610	-
1030303	FOSC-B-Tray-S-CWDM-MXDX 8CH Type C DTP-Expr-SA-NC (4351, 5761)	1030304	Cas-S-CWDM-MXDX 8CH Type A DTP-Express-SA-NC (43-53, 59-61)	-
1030309	CAS-DWDM-MXDX 4CH 100G ITU 20-23 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030310	CAS-DWDM-MXDX 4CH 100G ITU 24-27 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-2027-SA	CAS-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-SA-SC/APC all tai	-
1030311	CAS-DWDM-MXDX 4CH 100G ITU 28-31 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030312	CAS-DWDM-MXDX 4CH 100G ITU 32-35 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-2835-SA	CAS-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-SA-SC/APC all tai	-
1030313	CAS-DWDM-MXDX 4CH 100G ITU 36-39 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-3643-SA	CAS-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-SC/APC all tai	-
1030314	CAS-DWDM-MXDX 4CH 100G ITU 40-43 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-3643-SA	CAS-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-SA-SC/APC all tai	-
1030315	CAS-DWDM-MXDX 4CH 100G ITU 44-47 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-4451-SA	CAS-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-SC/APC all tai	-
1030316	CAS-DWDM-MXDX 4CH 100G ITU 48-51 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-4451-SA	CAS-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-SA-SC/APC all tai	-
1030317	CAS-DWDM-MXDX 4CH 100G ITU 52-55 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-5259-SA	CAS-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-SC/APC all tai	-
1030318	CAS-DWDM-MXDX 4CH 100G ITU 56-59 DTP-UG-EXP-SC/APC-NC	OPCAS-MD08-5259-SA	CAS-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-SA-SC/APC all tai	-
4005611	DWDM Mx/DMx, 4CH, ITU25, 27, 29, 31, LGX, SA	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-
4005612	DWDM Mx/DMx, 4CH, ITU35, 37, 39, 41, LGX, SA	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
4005613	DWDM Mx/DMx, 4CH, ITU43, 45, 47, 49, LGX, SA	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
4005614	DWDM Mx/DMx, 4CH, ITU53, 55, 57, 59, LGX, SA	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
4037353	CAS-DWDM-100G-MXDX-8CH ITU16-23, OADM LP	1030034	LGX-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-LA	-
4037354	CAS-DWDM-100G-MXDX-8CH ITU25-32, OADM LP	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-
4037355	CAS-DWDM-100G-MXDX-8CH ITU34-41, OADM LP	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
4037356	CAS-DWDM-100G-MXDX-8CH ITU43-50, OADM LP	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
4037357	CAS-DWDM-100G-MXDX-8CH ITU52-59, OADM LP	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
4040757	LGX-DWDM-100G-MXDX Dual 8Ch ITU16-23, LPTP	1030034	LGX-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-LA	-
4040758	LGX-DWDM-100G-MXDX Dual 8Ch ITU25-32, LPTP	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4040759	LGX-DWDM-100G-MXDX Dual 8Ch ITU34-41, LPTP	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
4040760	LGX-DWDM-100G-MXDX Dual 8Ch ITU43-50, LPTP	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
4040761	LGX-DWDM-100G-MXDX Dual 8Ch ITU52-59, LPTP	1030038	LGX-DWDM-MXDX 8CH 100G ITU52-59 DTP-UG-EXP-LA	-
4044048	1RU-DWDM-100G-MXDX-Dual 8CH ITU52-59, OADM LP	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
4044049	1RU-DWDM-100G-MXDX-Dual 8CH ITU43-50, OADM LP	1030037	LGX-DWDM-MXDX 8CH 100G ITU44-51 DTP-UG-EXP-LA	-
4044050	1RU-DWDM-100G-MXDX-Dual 8CH ITU34-41, OADM LP	1030036	LGX-DWDM-MXDX 8CH 100G ITU36-43 DTP-UG-EXP-LA	-
4044051	1RU-DWDM-100G-MXDX-Dual 8CH ITU25-32, OADM LP	1030035	LGX-DWDM-MXDX 8CH 100G ITU28-35 DTP-UG-EXP-LA	-
4044052	1RU-DWDM-100G-MXDX-Dual 8CH ITU16-23, OADM LP	1030034	LGX-DWDM-MXDX 8CH 100G ITU20-27 DTP-UG-EXP-LA	-
C102287-085	Jmpr, SA-SA, 7m	4000668	(JMPR-9SS-2-S-SA-SA-010) Jmpr, SM Sx, 2mm, Std, SA-SA, 10m	-

Product Migration Options

Customers are encouraged to migrate to the alternate optical passives as shown in Table 2. More information about these products can be found at: <http://www.cisco.com/c/en/us/products/video/optical-passive-components/datasheet-listing.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Prisma Optical Passives (Select DWDM Products) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)