

End-of-Sale and End-of-Life Announcement for the Cisco uBR10012 Performance Routing Engine 4

EOL10468

Cisco announces the end-of-sale and end-of-life Cisco uBR10012 Performance Routing Engine 4. The last day to order the affected product(s) is February 28, 2016. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

 Table 1.
 End-of-Life Milestones and Dates for the Cisco uBR10012 Performance Routing Engine 4

Milestone	Definition	Date	
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	es the end-of-sale and end-of-life of a product August 30, 2015	
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 28, 2016	
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 28, 2016	
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 27, 2017	
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 27, 2017	
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 27, 2017	
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	May 25, 2020	
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete ". Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	February 28, 2021	

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ESR-PRE4	Performance Routing Engine 4	See Product Migration Options section for details.	Performance Routing Engine 5	-
ESR-PRE4-UPG=	PRE4 upgrade bundle	See Product Migration Options section for details.	Performance Routing Engine 5	-
ESR-PRE4/R	Performance Routing Engine 4	See Product Migration Options section for details.	Performance Routing Engine 5	-
ESR-PRE4=	Performance Routing Engine 4	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT10G	Bundle incl. 1 PRE4, 1 DTCC, 1 4-SPA SIP, 1 1x10 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT10G-HA	Bundle incl. 2 PRE4, 2 DTCC, 2 4-SPA SIP, 2 1x10 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT 10G-HA=	Bundle incl. 2 PRE4, 2 DTCC, 1 4-SPA SIP, 2 1x10 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT10G=	Bundle incl. 1 PRE4, 1 DTCC+, 1 4- SPA SIP, 1 1x10 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT5G	Bundle incl. 1 PRE4, 1 DTCC+, 1 4- SPA SIP, 1 5x1 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-
UBR10-P4DT5G-HA	Bundle incl. 2 PRE4, 2 DTCC, 2 4-SPA SIP, 2 5x1 GE WAN SPA	See Product Migration Options section for details.	Performance Routing Engine 5	-

Product Migration Options

Customers are encouraged to migrate to the Performance Routing Engine 5. Information about this product can be found at: http://www.cisco.com/c/en/us/products/collateral/video/ubr10000-series-universal-broadband-routers/data-sheet_c78-728258.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco uBR10012 Performance Routing Engine 4 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Take back and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more Information about the Cisco uBR10012 Performance Routing Engine 5 , visit http://www.cisco.com/c/en/us/products/collateral/video/ubr10000-series-universal-broadband-routers/data_sheet_c78-728258.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html

http://www.cisco.com/en/US/products/prod warranties listing.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-735721-00 08/15

^{**} For more information about the Cisco Product Warranties, go to: