# Software for Support of -B Domain Access Points

#### **Contents**

Introduction

<u>Table 1 - Software releases with -B domain AP support</u> Special Note Regarding the AP802

### Introduction

Starting May 1, 2016, the Federal Communications Commission (FCC) restricted distribution of new -A domain access points in the United States. A new -B domain has been introduced to comply with the new FCC regulations. Cisco has released new AP SKUs for the -B domain - the following table shows in which software releases -B domain support is introduced.

For more information on the FCC change, see the New -B Domain Product Bulletin.

## Table 1 - Software releases with -B domain AP support

7.4.150 8.0.13 8.2.11 8.3.10 IOS-2.0 0.0 2.0 **IOS-XE IOS-XE IOS-XE Polaris Polaris AP Series** XΕ (15.2(2 (15.3( (15.3( (15.3( 3.6.5 3.8.2 3.9.0 16.1.3 16.2.2 3.7.4 )JB6) 3)JA7) 3)JC1) 3)JD) AP-3700i/e AP-2700i/e AP-1700i AP-3700p AP-3600i/e AP-2600i/e AP-1600i/e AP-700i/w AP-1532i/e AP-1572 AP-1552 (IoT) IW-3702 AP803 (in IR829) ASA55xx

Pola

16.3

#### **Special Note Regarding the AP802**

(AP702 embedded)

The AP802 (embedded in various 800 series ISR models) is not available in a -B SKU. 800 series ISRs with -A SKU AP802s sold after May 1, 2016, are compliant with FCC regulations (and only

support the UNII-1 and UNII-3 bands.)